

**SECRET**

IDEA-1073-63

*Cy 4 of 4*

21 February 1963

25X1A

Dear

The following is the UR information from Det H for the month of January 1963.

Due to the TDY of the Special Equipment Supervisor the Monthly UR Report was submitted without the equipment malfunctions for that section. Request these additional malfunctions be added to the UR Report for the month of January from this detachment:

1-26 VACUUM VALVE ASSEMBLY, HK-737769-501, Serial Nbr 43, total cycles 2374. Magnetic locking of solenoid plunger caused by cadmium plating wearing off the inside of the solenoid. This solenoid has been replaced with one that has a nickle plated interior.

1-27 SHUTTER ASSEMBLY, HK-7381000, Serial Nbr 51, total cycles 3267. A wire broke from left limit switch S-3 N.O. terminal G& W wire to terminal block number 4. Wire broke where the insulation had been stripped and wire soldered to limit switch terminal. Wire replaced and all assemblies were inspected for this type of failure.

Sincerely,

SIGNED

25X1A

25X1A

25X1A

Info copy sent to

MD/OSA-DD/R  (21 Feb 63)

25X1A

Dist: Cy 1 - Addee  LAC)  
2 -  (Werner Robins)

25X1A

3 - MD/OSA-DD/R  
4 - RB/OSA-DD/R

**SECRET**